



## Models usage instructions

- We suggest using OrCAD v16.6 Hotfix-s032 or higher to avoid convergence problems and speed up the simulation.



- Before starting the simulation, make sure that the option "Initialize all flip-flops" is set to "0".



- In case of convergence problems, check the option “AutoConverge”.

